

# ERASURE REPORT



## Company information

Licensed to:	Blancco Oy Ltd.	Business location:	Joensuu
Erasure provider:	Testing	Erasure person:	Blancco Tester
Business name:	Testing		

## Operator information

mac:	00:01:02:dc:f0:e3	time:	12:42:00 PM
date:	Friday 27 January 2012		

## Erasure results information

<b>Disk</b>	Model: <b>SAMSUNG</b>	Type: <b>SV1021H</b>	Serial: <b>0266J1FR466144</b>
	Size: <b>172698624</b>	Bus: <b>IDE/ATA</b>	Sectors: <b>337302</b>
	Remapped sectors: <b>0</b>		
Method:	<b>U.S. Navy Staff Office Publication NAVSO P-5239-26</b>		Duration: <b>01:27:11</b>
Status:	<b>Erased</b>		
Information:	<b>3 overwriting rounds performed</b>		
Start time:	2012-01-27 12:41:38 (+0200)	End time:	2012-01-27 14:09:49 (+0200)

<b>Disk</b>	Model: <b>SAMSUNG</b>	Type: <b>HD080HJ</b>	Serial: <b>00KB205887000000</b>
	Size: <b>130690560</b>	Bus: <b>IDE/ATA</b>	Sectors: <b>255255</b>
	Remapped sectors: <b>0</b>		
Method:	<b>U.S. Navy Staff Office Publication NAVSO P-5239-26</b>		Duration: <b>00:32:02</b>
Status:	<b>Not erased</b>		
Information:	<b>User cancelled the erasure 1 overwriting rounds performed</b>		
Start time:	2012-01-27 12:41:38 (+0200)	End time:	2012-01-27 13:13:40 (+0200)

## Hardware information

Manufacturer:	Hewlett-Packard	Chassis type:	Desktop
Model:	HP d230 MT(DQ444A)	Serial:	CZC4101S2G
Version:	1.11		
Processor:	Intel(R) Celeron(R) CPU 2.20GHz, current speed:2200000000		
Memory bank:	528482304		
Total Memory:	504MB, Free memory banks:0		
Graphics card:	Intel Corporation 82845G/GL[Brookdale-G]/GE Chipset Integrated Graphics Device		

I hereby state that the data erasure has been carried out in accordance with the instructions given by the software provider.

DATA ERASURE EXECUTIVE

SUPERVISOR